2007 Lancair Super ES SN: ES-147 - Location 50R /Lockhart TX	**300 Hours**
Engine	20B 3-Rotor P-Port / 300 HP
Engine Controllers \ PSRU	RWS-PSRU 2.85:1 ,EC2,EM2
MT Electric Constant Speed Prop	MTV-18-B/193-53 / 3 Blade Composite
Avionics	
Advanced Flight Systems EFIS (Added in September 2013)	Model- 5800
Autopilot	Advanced EFIS Autopilot System *Round Control Head
GPS	AF-GPS, 5Hz GPS Antenna Module
Engine Monitor Board	AFS
MAP Key	AFS
ARINC	PN: 71400
Backup EFIS	Blue Mountain Sport
Navcom	Garmin SL30
Transponder	Garmin GTX 327
ADSB Receiver	AFS
Intercom	Flight Com
CO Guardian	Model 353
ELT	Ameri-King AK451-2D
Accessories	
Oxygen System	Mountain High
	(2) Single User Pulse Units
	CFFC-048 Composite Tank (needs re-cert)
Headsets	(2) Place - Lightspeed (different models)
General Information	
Stock Super ES Engine Mount was maintained for Continental Engine swap	
New spare factory cowling.	
MT Electric Prop may be convertible to hydraulic	
Dual Battery \ Dual Alternators	
Airframe is in protective primer. Body work is at 85-90%.	
Family is asking $82,000 with fresh annual, instrument check, in flying condition.	
New owner can have their mechanic complete annual and price will be reduced accordingly.	
I can assist with Rotary engine hardware sale as needed. Price will be reduced accordingly.	
Contact: Bobby Hughes 210-410-6206 \ bhughes@qnsi.net	